

Proactive preventative maintenance, per industry standards, is essential to any asset life extension program. However, some isolated phase bus systems lack accessibility inside the enclosure to ensure proper routine inspection and maintenance. EBI's welded inspection windows provides easy access to the internal isolated phase bus enclosure for necessary visual inspection and cleaning to maintain the health of your system critical electrical components and mitigate opportunities for a forced outage.

The inspection windows are compatible with all diameters of isolated phase bus duct and can be installed on generator low voltage and neutral bushing cabinets as well as GSU bushing cabinets. Installing EBI's welded inspection windows near existing seal off bushings allows for easy inspection and cleaning access to avoid potential catastrophic bushing failure.

CONTACT EBI TODAY FOR YOUR FREE ONSITE WALK-DOWN ASSESSMENT.



STEP 1 Opening is cut in the enclosure



STEP 2 Window base is welded into the enclosure



STEP 3 Window cover is secured in place



